



Video Products Technical Bulletin 30-2017-153

DATE: **December 11, 2017**

SUBJECT: **MANUAL CORRECTION—NOTES ON HDR
DISPLAY IN PERIODIC REPLACEMENT PARTS;
NOTES ON UPGRADING SOFTWARE VERSIONS**

MODEL: ***BVM-E171***
BVM-E171

DESCRIPTION

Correct the following manual as shown in Figure 1 and Figure 2.
BVM-E171 Service Manual, 1st Edition

SERIAL NO: **ALL**

*Italicized information in green applies to
customers outside the United States.*

NOTE: Add the bullet points in red.





Figure 1

DPMO17-039



SECTION 5 UPGRADE
5-1. UPGRADE METHOD

Note

- Do not remove the USB flash drive from the slot or disconnect the LAN cable between the monitor and the controller during upgrade.
- Do not turn off the monitor and the controller during upgrade.
- **Confirm the software version.**

If software is V1.01, software can be upgraded directly to V1.1 using the following procedure.

If software is V1.0, upgrade software to V1.01 first, and then upgrade software to V1.1. To acquire V1.01 software, contact Sony.

- **When upgrading software to V1.1, upgrade both the software and the FPGA.**

Figure 2