

Display

Date: **March 18, 1996**

Subject: **CORRECTING DARK PICTURE**

Model: **BVM-1315/1316/1316C/1915/1916**

Serial No: **ALL**

DESCRIPTION

The picture may become dark due to voltage exceeding the resistor rating of R18 on the C board. Replace R18 on the C board with

- One 1M Ω resistor, or
- Two 470k Ω resistors, connected in series

PARTS REQUIRED

Part No.	Description	Qty.
1-208-608-11	Res, 1M Ω	1
1-202-846-00	Res, 470k Ω	2