

**Display**Date: **May 15, 2000**Model: **BVM-D24**Subject: **W/B ADJUSTMENT**Serial No: **ALL****DESCRIPTION**

If input fh is approximately 15kHz (NTSC, PAL, SECAM) or if input is SDI 4fsc, when AUTO of the CONTROL PRESET is performed, WHITE BALANCE (W/B) may not be adjusted accurately.

To correct this condition, perform W/B procedure:

1. Warm up set.
2. Perform ADJ INT SIG in Setup/Extend menu.
3. Perform AUTO CONTROL PRESET adjustment for every input format.
4. Perform STD W/B.
5. Perform COL1 and COL2 W/B if necessary.
6. Verify white balance of each format with a 100% white picture.

If W/B of formats with fh of approximately 15kHz does not match W/B of other formats, perform CH SET W/B adjustment.