



Professional Video Monitor

Video Products Technical Bulletin 30-2012-092

DATE: **August 13, 2012**SUBJECT: **PARTS REGISTRATION—BEZEL ASSEMBLY AND
RELATED PARTS IN FRONT AND CHASSIS
BLOCK; OPERATING INSTRUCTIONS**MODEL: ***PVM-740***
PVM-740SERIAL NO: **ALL***Italicized information in green applies to
customers outside the United States.*

DESCRIPTION

A new bezel and related parts in the front and chassis block are available. (See Table 1.)

NOTE: Refer to the *PVM-740 Service Manual*, 1st Edition, Section 4 "Spare Parts."

APPLICABLE UNITS

Former Parts

Former parts are installed in units with the following serial numbers, and the model name plate indicates "Made in Japan."

7,000,001 and higher

7,200,001 and higher

New Parts

New parts are installed in units with the following serial numbers, and the model name plate indicates "Made in China."

3,000,001 and higher

5,000,001 and higher

ORDERING INFORMATION

To order parts online, go to: www.sony.com/servicesplus. For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

DPMO12-022R

Table 1

Ref. No.	Former		→	New		Compatibility and Comments
	Description	Part No.		Description	Part No.	
101	Bezel block	A-1769-122-A	→	Bezel assembly	X-2546-886-2	Former bezel block not compatible in Korea. New bezel assembly compatible in all regions. See Figure 1.
				Tally cover	4-146-127-01	Tally cover in former bezel block can be reused in new bezel assembly.
				Control panel sheet	4-146-143-02	Sheet in former bezel block cannot be reused in new bezel assembly.
				Screws, +B3×4	7-682-545-09	Screws in former bezel block can be reused in new bezel assembly.
116	Protection Plate	4-127-282-11	→	Protection Plate	4-127-282-01	New plate is compatible in all regions.
119	Heat conductive sheet (tab)	4-181-159-01	→	Heat conductive sheet (tab)	No longer available	Former sheet can be reused with new parts.
120	Cushion Bzl (H)	4-181-283-01	→	Cushion Bzl (H)	4-181-283-11	New cushions are compatible in all regions.
121	Cushion Bzl (V)	4-181-284-01	→	Cushion Bzl (V)	4-181-284-11	
—	PI tape on OLED module assembly (Ref No. 102)	—	→	PI tape on OLED module assembly (Ref No. 102)	4-282-041-01	Former tape on OLED cannot be reused. See Figure 2.
—	Operating instructions	4-176-661-01	→	Operating instructions	4-176-661-41	Former manuals cannot be used in Korea.
—	CD-ROM	4-176-662-01	→	CD-ROM	4-276-778-01	




Figure 1




Figure 2

NOTE: When using new PI tape on a new OLED module assembly, refer to the removed OLED assembly for exact positioning of the tape.
