

**Display**

---

Date: **March 11, 1996**Subject: **ENHANCED RELIABILITY OF  
ELECTROLYTIC CAPACITORS**Model: **BVM-1310/1311/1315/1316/1316C**  
**BVM-1910/1911/1912/1915/1916/2811**Serial No: **ALL****DESCRIPTION**

For enhanced reliability of electrolytic capacitors on the GA board (component side) in the power supply block, replace the following capacitors with improved parts.

- C7 (located between L3 and L4)
- C9 (located to the left of L4)
- C11 (located to the right of L9)
- C13 (located to the right of L9)

To order, use the following new part number :

**Cap, Elect, 470 $\mu$ F, 25V**  
**1-126-104-11**