

Display

Date: **September 25, 1995**Subject: **INFORMATION ON H. OUT TRANSISTOR**Model: **PVM-95/95E/96/96E/97**
PVM-135/136/137/145E/146ESerial No: **ALL****DESCRIPTION**

Irrespective of the descriptions in the service manual, use only a KTC 4371 transistor (P/N 9-906-868-01) for replacement of the horizontal output driver (H. OUT). Using any other component, including a BU406, will cause premature failure of the drive circuitry.

- For PVM-95, 95E, 135, and 145E, a KTC4371 is the correct component for Q402 on the A board.
- For PVM-96, 96E, 97, 136, 137, and 146E, a KTC4371 is the correct component for Q505 on the A board.