Display



WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

## Video Products Technical Bulletin 30-2008-108

DATE: July 28, 2008

SUBJECT: MANUAL CORRECTION—PWB FRAME IN CHASSIS

MODEL: **PVM-5041Q** 

PVM-5041Q/1 PVM-5041Q/4 PVM-5041Q/5 PVM-5041Q/6 PVM-6041Q/C PVM-6041QM/1 PVM-6041QM/1 PVM-6041QM/2 PVM-6041QM/3 PVM-6041QM/4 PVM-6041QM/5 PVM-6041QM/5

PVM-6041QM/7 PVM-6041QM/8

SERIAL NO: ALL

Italicized information in green applies to customers outside the United States.

## DESCRIPTION

Correct the following manuals as shown in Figure 1.

PVM-5041Q Service Manual (Rev. 1)

PVM-6041QM Service Manual, 2nd Edition

**NOTE:** The PWB frame assembly consists of six pieces of the PWB frame.

DPMO07-035




Figure 1

Broadcast Professional Products Asia • Sony Australia • Broadcast Professional Products Europe • Sony Canada Ltd. • Sony Electronics Inc. USA • Sony Broadcast and Professional Latin America