



**Display**

Date: **April 3, 2000**

Model: **BVM-D9H1A, BVM-D9H1E, BVM-D9H1U**  
**BVM-D9H5A, BVM-D9H5E, BVM-D9H5U**

Subject: **FLUCTUATION OF PICTURE SIZE**

Serial No: **SEE TEXT**

**DESCRIPTION**

Picture size may fluctuate when switching input signals. To correct the symptom, perform the following modification procedure.

**SERIAL NUMBERS**

BVM-D9H1A 2,000,001–2,000,005  
 BVM-D9H1E 2,000,001–2,000,010  
 BVM-D9H1U 2,000,001–2,000,305  
 BVM-D9H5A 2,000,001–2,000,010  
 BVM-D9H5E 2,000,001–2,000,010  
 BVM-D9H5U 2,000,001–2,000,430

**PARTS REQUIRED**

Part No.	Description	Qty.
1-164-005-91	Cap, Chip, 0.47 $\mu$ F	1

**MODIFICATION PROCEDURE**

**D Board**

Replace C2516 (0.22 $\mu$ F) with a 0.47 $\mu$ F capacitor.