

**HDVS® Display**Date: **October 19, 1998**Subject: **IMPROVED RELIABILITY**Model: **HDM-1230, HDM-1730**Serial No: **ALL****DESCRIPTION**

Enhance the reliability of switching regulator by replacing two (C602 and C603) 4.7 μ F/350V capacitors on TK-15 board with 10 μ F/350V capacitors.

PARTS REQUIRED

Part No.	Description	Qty.
1-110-573-51	Cap, 10 μ F/350V	2