



Display

# Video Products Technical Bulletin 30-2003-214

DATE: **December 1, 2003**

SUBJECT: **MANUAL CORRECTION—FLYBACK  
TRANSFORMER ASSEMBLY**


MODEL: **PVM-14M2MDU**  
***PVM-14M2MDE***  
***PVM-14M2MDA***  
**PVM-20M2MDU**  
***PVM-20M2MDE***  
***PVM-20M2MDA***

**DESCRIPTION**

Correct the *PVM-14M2MDU/14M2MDE/14M2MDA/20M2MDU/20M2MDE/20M2MDA Service Manual* as shown in Figure 1.

SERIAL NO: **ALL**

*Italicized information in green applies to customers outside the United States.*



**Figure 1**

DPM001-051