

WORLDWIDE TECHNICAL BULLETINS FOR BROADCAST AND PROFESSIONAL PRODUCTS

Broadcast Products Technical Bulletin 20-2008-218

Display

DATE: November 3, 2008 SUBJECT: PARTS REGISTRATION—DEFLECTION YOKE

MODEL: **BVM-A32E1WM**

BVM-A32E1WS BVM-A32E1WU BVM-D32E1WA BVM-D32E1WE BVM-D32E1WU

SERIAL NO: ALL

Italicized information in green applies to customers outside the United States.

DESCRIPTION

When stock for the following deflection yoke (DY) is depleted, the part will no longer be available:

Description Part No.

Deflection Yoke (Y32TXD-T) 1-451-521-11

When replacing the CRT, remove the DY from the former CRT and install it in the new CRT. Replace the DY only when defective.

ORDERING INFORMATION

To order parts online, go to: http://www.sony.com/servicesplus. For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

DPMO07-031