

**Still Image—Printer**Date: **August 21, 2000**Model: **OEP3, UP-50**Subject: **HUE CHANGE WHEN PVM-N SERIES
MONITOR IS CONNECTED**Serial No: **ALL****DESCRIPTION**

When feeding a signal from S-VIDEO output to a PVM-N series monitor such as PVM-14N5U, PVM-14N6U, PVM-20N5U or PVM-20N6U, hue may change. To correct the symptom, perform the following modification procedure.

MODIFICATION PROCEDURE

1. Enter service mode. (See PVM-14N5A Service Manual, pages 3-1–3-2.)
2. Display service item 7: "Y DLY NTSC Y/C".
3. Change setting from "4" to "9".
4. Display service item 24: "C BPF NTSC Y/C".
5. Change setting from "0" to "1".
6. Save changed settings to EEPROM.
7. Exit service mode.
8. Turn unit off.

CONFIRMATION

1. Turn monitor on.
2. Verify color bars display properly when feeding a signal to S-VIDEO input.

NOTE: No symptoms should occur if signals are input from sources other than the printer.