



# Video Products Technical Bulletin 30-2017-006

DATE: February 20, 2017

SUBJECT: PARTS REGISTRATION—CONNECTION CABLE  
(SMF-700)

MODEL: **BVM-E170**  
*BVM-E170A*  
**BVM-E170A**  
*BVM-E171*  
**BVM-E171**  
**BVM-E250**  
*BVM-E250A*  
**BVM-E250A**  
*BVM-E251*  
**BVM-E251**  
**BVM-F170**  
*BVM-F170A*  
**BVM-F170A**  
**BVM-F250**  
*BVM-F250A*  
**BVM-F250A**  
**BVM-L170**  
**BVM-L230**  
**BVM-L231**  
**PVM-L1700**  
**PVM-L2300**  
**PVM-L3200**

**DESCRIPTION**

SMF-700 is now available as a service part:

Description	Part No.
Connection cable (SMF-700)	1-830-578-22

---

**NOTE:** SMF-700 is no longer available through the sales channel.

---

**ORDERING INFORMATION**


---

To order parts online, go to: [www.sony.com/servicesplus](http://www.sony.com/servicesplus). For service or parts ordering assistance, refer to the following document, which lists all contact telephone numbers:

Technical Bulletin 00-1999-000

---

SERIAL NO: ALL

*Italicized information in green applies to customers outside the United States.*

DPMO17-002