



# Video Products Technical Bulletin 30-2003-231

DATE: **December 29, 2003**

SUBJECT: **PARTS REGISTRATION—BEZEL ASSEMBLY**

MODEL: **PVM-20S1WU**

**DESCRIPTION**

The bezel assembly is now available as service part number **X-4035-556-1**. Correct the *PVM-20S1WU Service Manual, Supplement-1* as shown in Figure 1.

SERIAL NO:

PVM-20S1WU 2,010,001 and Higher

	Part No.	Description
ADD →	X-4035-556-1	BEZEL ASSEMBLY

**Figure 1**

---

**NOTE:** If your unit is earlier than serial number 2,010,001 and you use the new bezel assembly, you must replace the H board (A-1372-477-A).

---