

Sony Electronics Inc.
Business and Professional Products Group
Technical Publications
3300 Zanker Road, San Jose, California 95134

Display

Date: **January 16, 1995**

Subject: **FIRMWARE UPGRADE—VERSION 5.0**

Model: **BKM-1450/2056**

Serial No: **2,002,191 AND HIGHER (BKM-1450)**
2,003,439 AND HIGHER (BKM-2056)



DESCRIPTION

Firmware version 5.0 is now available. The new firmware implements the auto setup function for 30-inch BVM monitors. Figure 1 shows the luminance setup in the service mode menu. To install the new firmware, replace IC3 on the BN board with the new EPROM.

PARTS REQUIRED

Part No.	Description	Qty.
8-759-274-31	EPROM (BN Board/IC3)	1




Figure 1

