



Display

Video Products Technical Bulletin 30-2002-287

DATE: **December 23, 2002**SUBJECT: **VIDEO NOISE WITH BKM-B10 VIDEO INPUT
ADAPTOR BOARD**MODEL: **PFM-50C1
PFM-50C1E**

SERIAL NO:

PFM-50C1	2,000,001 and Higher
PFM-50C1E	2,000,001 and Higher

DESCRIPTION

To prevent video noise when using the BKM-B10 video input adaptor board, remove the gasket from the BKM-B10 board. (See Figure 1.)




Figure 1

NOTE: You do not need to remove the gasket when using BKM-B10 in the following models:

- PFM-42B1
- PFM-32C1

DPMO02-031