



# Video Products Technical Bulletin 30-2004-001

DATE: **January 12, 2004**

SUBJECT: **MANUAL CORRECTION—BEZEL ASSEMBLY**

MODEL: **PVM-14M2U**  
**PVM-14M4U**  
*PVM-14M2E*  
*PVM-14M4E*  
*PVM-14M2A*  
*PVM-14M4A*


**DESCRIPTION**

Correct the *PVM-14M2U/14M4U/14M2E/14M4E/14M2A/14M4A Service Manual*, Supplement-1 as shown in Figure 1.

SERIAL NO:

PVM-14M2U 2,010,001 and Higher  
 PVM-14M4U 2,010,001 and Higher  
*PVM-14M2E 2,010,001 and Higher*  
*PVM-14M4E 2,010,001 and Higher*  
*PVM-14M2A 2,010,001 and Higher*  
*PVM-14M4A 2,010,001 and Higher*

*Italicized information in green applies to customers outside the United States.*



**Figure 1**

**NOTE:** If your unit is earlier than serial number 2,010,001 and you use the new bezel assembly, you must replace the H board (A-1372-477-A).