## SONY

Display

16

Subject: ENHANCED ELECTROLYTIC CAPACITORS

## Date: June 14, 1999

Model: BVM-8044QD, PVM-5041Q, PVM-8040 PVM-8041Q, PVM-8044Q, SSM-8040

Serial No: ALL

## DESCRIPTION

To enhance the reliability of the unit when used in a high temperature environment, replace the former electrolytic capacitors listed in Table 1, which reside on the D board (side A), with their respective new parts (105° C rating).

Part	Value	Former P/N.	New P/N
C527	100 <i>µ</i> F, 50V	1-124-122-51	1-107-910-11
C529	47 <i>µ</i> F, 50V	1-124-910-51	1-107-909-11
C532	1000 <i>µ</i> F, 50V	1-124-557-51	1-107-914-11
C537	220 <i>µ</i> F, 35∨	1-124-484-51	1-107-894-11

Table 1

DPM099-006

Page 1 of 1

Broadcast Professional Products Asia • Sony Australia • Sony Broadcast Professional Europe • Sony Canada Ltd. • Sony Electronics Inc. USA • Sony Products Professional Latin America)

**Video Products Technical Bulletin 1999** Worldwide Technical Bulletins for Broadcast and Professional Products