

## Display

Date: **June 29, 1992**


Subject: **BATTERY COMPARTMENT PLATE**

Model: **PVM-8041Q**

Serial No: **2,000,500 AND LOWER**

### DESCRIPTION

The battery compartment plate may sometimes protrude out of the compartment when the blue tape is removed. To correct this, push the plate down and inward as shown in Figure 1.



*Figure 1*