



Display

Date: **May 18, 1998**

Subject: **CHANGE OF REPAIR PARTS, TOP COVER**

Model: **PVM-1954Q**

Serial No: **ALL**

DESCRIPTION

Since the stock of the top cover has been depleted, the service part for current model 20M series has been substituted. (See Table 1.)

Former		New
Top Cover 4-043-675-11	➔	Top Cover 4-057-973-11

Table 1

Top Cover For	Color	Material
54Q Series	2B	Steel coated with vinyl chloride
20M Series	C2*	Painted steel

*Color (gray) is brighter than 2B.